


# Shell EPW Wells HSE Early Learning Bulletin

**Fountain No:**137054 **Location:** GOM **Date:** 25-Jul-2007 **Risk Ranking:** Actual – Level 2 People, Potential - D3 People Med

**What happened:** MTC-IP INJURES FINGER WHILE LANDING TOOL BASKET-IP was performing duties of designated banksman while landing tool basket with crane on rig floor. Fellow roustabout was assisting IP with load. IP placed both hands on basket while basket was being landed. One side of basket landed on deck of drill floor and the opposite side of basket became at rest on the PRS tracks. Load shifted inside basket resulting in IP's finger becoming caught between face plate of tool and lip of basket. IP removed face plate of tool from atop finger with assistance from aft driller. IP reported incident to supervisor and medic. Medic evaluated, treated and evacuated IP to shore for further evaluation and treatment per consultation with company physician.



## Preliminary Learning Points

- Proper engineering of basket for storage of tools in basket needs to be considered by vendors when shipping tools.
- Tools in basket to be positioned in an orderly fashion to prevent loads shifting while being lifted by crane.
- Designated Banksman to follow policy of keeping hands off of load.
- A minimum of two tag lines to be positioned at opposite corners on all loads.
- Employees landing loads do not need to place hands on basket but utilize tag lines in positioning of loads.
- Heighten awareness of identifying hazards and stopping the job when the hazards are identified.



This Learning Bulletin provides preliminary learnings. A detailed investigation is pending. Shell EPW.